


# MONUMENT RECORD

STATE OF INDIANA ~ COUNTY OF MONROE

Section 33, Township 9 North, Range 1 East,


Monument Description & Remarks: Found sandtone leaning but solid in ground, stone is 0.30' x 0.80' x 0.60' out of ground, stone has a chisled "x" on top.



I, Ben E. Bledsoe, Registered Land Surveyor, here by certify that this document was prepared under my direction in accordance with the provisions of Section 17-3-64-4 through 17-3-64-8 of the Indiana Code, being Acts of 1965, Chapter 319; this 6th day of January, 2005 A.D.

*Ben E Bledsoe*

Indiana Registered Land Surveyor No. S0559



# MONUMENT RECORD


STATE OF INDIANA - COUNTY OF MONROE

SECTION 33, TOWNSHIP 9 NORTH, RANGE 1 EAST

### MONUMENT DESCRIPTION & REMARKS

FOUND SANDSTONE STONE LEANING BUT SOLID IN GROUND, STONE IS  
0.30'X 0.80'X 0.60' OUT OF GROUND, STONE HAS A CHISLED "X"  
ON TOP.

## RECOVERY TIE DRAWING



STATE OF INDIANA

COUNTY OF MONROE

I, EDMUND O. FARKAS HEREBY CERTIFY THAT THIS DOCUMENT WAS PREPARED UNDER MY DIRECTION IN ACCORDANCE WITH THE PROVISIONS OF SECTION 17-3-64-4 - 17-3-64-8 OF THE INDIANA CODE, BEING ACTS OF 1965, CHAPTER 319; AND THE ABOVE DATA IS GIVEN UNDER MY HAND AND SEAL THIS 6TH DAY OF FEBRUARY, 19 85 A.D.

SPACE  
RESERVED  
FOR  
RECORDING  
OFFICER.

INDIANA REGISTERED LAND SURVEYOR NO. \_\_\_\_\_

OR \_\_\_\_\_

UNITED STATES GOVERNMENT AGENCY

TITLE

TOWNSHIP:  
BENTON S.

CORNER I.D.

M-46